

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**




Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- ✓ • TEXT CUT OFF AT TOP, BOTTOM OR SIDES , *LINES*
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**






FIG. 2a



FIG. 2b






FIG. 2c



Typical GP Extension with indicating Collar



MZST Mojave Packer / Frac Extension, Sliding sleeve Open, Go-No-go Collar in land in Position

FIG. 4

3/6







FIG. 5

4/6






FIG. 8a-




FIG. 8




FIG. 9




FIG. 9a




FIG. 10




FIG. 10a

6/6

